

PowerLogic™ ION8800 series firmware version 372

PowerLogic™ ION8800 series firmware version 372 contains a number of new features and changes that are designed to help improve the security of your meter.

We highly recommend that you upgrade your firmware to this version.

This document lists the new functionality in firmware version 372, as well as information on how to obtain additional information and resources.

Additional information and resources

Visit www.se.com to download:

- The firmware upgrade files.
- The latest user manual, datasheets, and installation guides.

NOTE: There are no new frameworks in this release.

Prerequisites

- ION Setup 3.2.20337.02 or higher. To check your version of ION Setup, in ION Setup click **Help > Check for Updates**.

New functionality

ION protocol update

An update to the ION protocol was made to address a vulnerability that may reset the meter.